

Dial Indicators and Digital Indicators

Nomenclature



PG
27

Dial faces

0.01mm



0.001mm



Continuous dial (Reverse reading)

Balanced dial (One revolution)

Continuous dial (Double scale spacing)

Balanced dial (One revolution)

- Continuous dial: For direct reading
- Balanced dial: For reading the difference from a reference surface
- Reverse reading dial: For depth or bore gage measurement
- One revolution dial: For error-free reading of small differences